Gain and Offset (4)-2

>> Summary of Offset





error bars are rms spreads