Gain and Offset (4)-1

>> Summary of Gain





error bars are rms spreads